




Belt Splicing Recommendations

One ply strength	\leq 255 Kg/cm/ply	$>$ 255 Kg/cm/ply
Total belt strength	\leq 1020 Kg/cm	$>$ 1020 Kg/cm
Cover Rubber Thickness	0 ~ 6.5 mm	$>$ 6.5 mm
Cover Rubber Grade	Grade M, JIS-S, JIS-G, JIS-L	Grade M, JIS-S, JIS-G JIS-L
General Use	QB	QB, UIP, SAR
Oil Resistance	OR-210, OR-220	OR-210, OR-220
Heat Resistance	HC – 510, HC-513	HC-510, HC-513, HC-710
Fire Resistance	-	FR-300 T
Chemical Resistance	-	CR



TOOLS

COLD SPLICING



HOT SPLICING

SALES ENGINEERING



9 Step Cold Splicing

1. Drawing
2. Cutting and Peeling
3. Grinding
4. Cleaning
5. Cementing
6. Joining
7. Rolling
8. Finishing
9. Checking

Material Cold
Splicing





[BACK](#)

9 Step Cold Splicing

1. Drawing

Misal Spec. 1000mm x EP-200 x 3P



Cold Splicing Calculation

$$L = (0.3 \times B) + (S \times (n-1)) + 25 + 50$$

L = Splice Length [mm]

B = Belt Width (mm)

S = Step Length (mm)

n = Total Plies

Step Length Table

Fabric Strength (Kg/cm)	Step Length (mm)
50 – 120	150
121 – 150	200
151 – 200	250
201 – 250	300
251 – 350	350



9 Step Cold Splicing

[BACK](#)

2. Cutting And Peeling

- Cut and Peel Cover Rubber
- Cut Edge Gum
- Cut and Peel Canvas
- Cut and Smooth-down Canvas



[BACK](#)

9 Step Cold Splicing

3. Grinding

Grinder & Coarsening Surface of crosscut Cover Rubber



Coarsening the surface cover with scratch of brush

Do not hurt canvas when grinding



RUBBER CONVEYOR BELT



SALES ENGINEERING



RUBBER CONVEYOR BELT



SALES ENGINEERING



BACK

9 Step Cold Splicing

4. Cleaning



Cleaning Surface of Extension with Wire Brush

Cleaning Surface of Extension with Dust-Cloth Wetted with Cleaning Solvent

Dust-Cloth have to be clean



9 Step Cold Splicing

[BACK](#)

5. Cementing



First Step of Gluing:

Dab the BANDO Sunpat-ECO Glue till flatten, then wait momentarily around 10~20 Minute

During cementing cement brush has to be pressed, so glue can entering pores of canvas



Second Step of Gluing:

Dab again the BANDO Sunpat-ECO Glue till flatten

Touch the surface of glue with you nail to make sure that the glue have run dry and will not patch to your nail



6. Joining

9 Step Cold Splicing

[BACK](#)



Attach Plastic layer

Centering

Attach both sides of extension, by paralleling the center line mark

Joining Belt

Joint/ gumming both extension back part and discharged its plastic layer.



RUBBER CONVEYOR BELT



BACK



SALES ENGINEERING




BACK

9 Step Cold Splicing

7. Rolling

Rolling must be conducted toward vertical and horizontal extension surface



[BACK](#)


9 Step Cold Splicing

8. Finishing

Cut the remains tip of
Cover Rubber

Buffing the joining surface

Neaten Edge Side
Extension with Buffing
machine




[BACK](#)

9 Step Cold Splicing

9. Checking

Straightness and Appearance Inspection




Standard h = less than 0.1%


$$\left(\frac{h}{\text{distance from 1 to 4 mm}} = 0.1\% \right)$$



Thick Inspection



Width Inspection



Length Inspection

